

# AutoShack Weekly Tip




**ASWTDecember222019**

## EVAP FAILURE\_VAPOR ONLY PLEASE\_NO LIQUID

- EVAP (EVAPorative Emission) system failure is one of the most common performance issues on the Ghanaian road.
- A large number of these failures are due to people overfilling their fuel tanks.
- There is an EVAP canister on your vehicle that is meant to capture fuel vapors ONLY.
- When you overfill your tank you may get liquid fuel into it your canister.
- Doing this regularly will spell the beginning of your troubles and endless trips to your mechanic.
- To learn more about this, watch Maintenance Motorway Season 1 Episode 5 on our YouTube Channel.

EVAP Canister- Captures vapors only. Damaged by liquid.





- Click links below to visit/contact us to learn more about us and how we might be able to assist you.
  - t: +233-57-6974225
  - e: [ask@autoshackghana.com](mailto:ask@autoshackghana.com)
  - w: [www.autoshackghana.com](http://www.autoshackghana.com)
  - Shop: [www.shop.autoshackghana.com](http://www.shop.autoshackghana.com)
- A majority of the tip topics are suggested by others based on their experiences.
- Consider helping others to benefit from your experiences by suggesting a topic for our tip bank based on your car troubles, experiences or observations.